





# HL510Prblue-3125 < 0,50 l/sec DN 40/50



**D** BODENABLAUF      **TR** YER SÜZGEÇİ  
**IT** SCARICO A PAVIMENTO      **CZ/SK** PODLAHOVÁ VPÚST  
**GB** FLOOR DRAIN      **HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ      **RO** SIFON DE PARDOSEALĂ  
**PL** WPÚST PODLOGOWY      **RU** ТРАП  
**SI** TALNI ODTOK      **BG** ПОДОВ СИФОН

27.02.2024



# HL510Prblue-3125 < 0,50 l/sec DN 40/50



**D** BODENABLAUF      **TR** YER SÜZGEÇİ  
**IT** SCARICO A PAVIMENTO      **CZ/SK** PODLAHOVÁ VPÚST  
**GB** FLOOR DRAIN      **HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ      **RO** SIFON DE PARDOSEALĂ  
**PL** WPÚST PODLOGOWY      **RU** ТРАП  
**SI** TALNI ODTOK      **BG** ПОДОВ СИФОН

27.02.2024



# HL510Prblue-3125 < 0,50 l/sec DN 40/50



**D** BODENABLAUF      **TR** YER SÜZGEÇİ  
**IT** SCARICO A PAVIMENTO      **CZ/SK** PODLAHOVÁ VPÚST  
**GB** FLOOR DRAIN      **HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ      **RO** SIFON DE PARDOSEALĂ  
**PL** WPÚST PODLOGOWY      **RU** ТРАП  
**SI** TALNI ODTOK      **BG** ПОДОВ СИФОН

27.02.2024

# HL510Prblue-3125 < 0,50 l/sec DN 40/50



**D** BODENABLAUF      **TR** YER SÜZGEÇİ  
**IT** SCARICO A PAVIMENTO      **CZ/SK** PODLAHOVÁ VPÚST  
**GB** FLOOR DRAIN      **HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ      **RO** SIFON DE PARDOSEALĂ  
**PL** WPÚST PODLOGOWY      **RU** ТРАП  
**SI** TALNI ODTOK      **BG** ПОДОВ СИФОН

27.02.2024